

FUEL/WATER SEPARATOR SPIN-ONS with Open Port for Bowl

BF1222-O



Contains: Port Thread: 3-12, Integral Port Seal
Fits: Applications Using BF1222 or BF1222-SP Requiring an Open Port for Bowl
Replaces: Ford F2TZ-9N-184-A; Motorcraft FD3375
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 4 1/8 (104.8)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1223-O



Contains: Port Thread: 3 3/4-10, Integral Port Seal
Fits: Ford Trucks
Replaces: Ford F1HZ-9365-A; Motorcraft FD3368
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 7/32 (132.6)
F. Gskt.: [1] Included
I. Gskt.: [1] Included

BF1287-O



Contains: Port Thread: M85 x 2.5, Integral Post Seal
Fits: Komatsu HD465-7, HD605-7 Dump Trucks
Replaces: Komatsu 600-311-3210, 600-319-3240
Thread: 1 1/4-12
O.D.: 4 7/8 (123.8)
Length: 9 29/32 (251.6)
F. Gskt.: [2] Included
I. Gskt.: [1] Included

BF1288-O



Contains: Port Thread: M85 x 2.5, Integral Post Seal
Fits: Komatsu Dump Trucks, Equipment
Replaces: Komatsu 600-311-4510, 600-319-4500
Thread: 1 1/4-12
O.D.: 4 7/8 (123.8)
Length: 9 29/32 (251.6)
F. Gskt.: [1] Included
I. Gskt.: [1] Included

BF1290-O



Contains: Port Thread: B80 x 3.0
Replaces: CLARCOR Filtration (China) WBF219B; Foton Lovol 1307211500005
Thread: 1-14
O.D.: 4 11/32 (110.3)
Length: 6 13/32 (162.7)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1292-O



Contains: Port Thread: M95 x 2.5, Integral Port Seal
Fits: Deutz Engines; Deutz-Fahr, Fendt Tractors
Replaces: Deutz 4291642, Fendt F339202060120; Iveco 42549295; Mercedes-Benz 4771602, A0004771602; Racor R90T-D-MAX
Thread: 1-14
O.D.: 4 5/32 (105.6)
Length: 6 5/16 (160.3)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1294-O



Contains: Port Thread: 3 3/4-10, Integral Post Seal
Fits: Scania Genset Engines
Replaces: Scania 1518512; SF-Filter SK3360
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 7 5/32 (181.8)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1295-O



Contains: Port Thread: 3 3/4-10
Replaces: CLARCOR Filtration (China) CX1010; DCD 4102H1520
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 1/32 (127.8)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1296-O



Contains: Port Thread: B80 x 3.0
Fits: Doosan Equipment
Replaces: CLARCOR Filtration (China) WBF219B1; Sinotruk 13050733
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 13/32 (162.7)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1297-O



Contains: Port Thread: B80 x 3.0
Replaces: CLARCOR Filtration (China) WBF219H; Weichai Power 612630080088
Thread: 1-14
O.D.: 4 9/32 (108.7)
Length: 9 3/32 (231.0)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1299-O



Contains: Port Thread: 3 3/4-10
Replaces: Yuchai Watyuan 612630080205
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 7 13/16 (198.4)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1329-O



Contains: Port Thread: 3 3/4-10, Integral Port Seal
Fits: Blue Bird Buses; Racor 690R Series Filter Systems; Freightliner, Oshkosh, Scania, Volvo Trucks
Replaces: DAF 1296851; Scania 1393640; Racor R90P; Volvo 8159975
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 5/16 (160.3)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1345-O



Contains: Port Thread: 3-12
Fits: International Engines, Trucks
Replaces: International 1618385-C91; Donaldson P550729
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 9/32 (134.1)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1346-O



Contains: Port Thread: M95 x 2.5
Fits: Freightliner Trucks
Replaces: Racor S3226P; Donaldson P550554; Fleetguard FS19593; Luber-finer LFF5850
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 5/16 (160.3)
I. Gskt.: [1] Included
O-Ring: [1] Included
Related To: BF1346 (Standard Version) BF1346-SP (Sensor Port Version)

BF1348-O



Contains: Port Thread: M95 x 2.5
Fits: Blue Bird Buses; Freightliner, Hino, Peterbilt Trucks
Replaces: Racor S3225P; Donaldson P550436; Fleetguard FS19521; Luber-finer LFF5849; Wix 33630
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 3/16 (131.8)
A. Gskt.: [1] Attached
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1366-O



Contains: Port Thread: M80 x 2.5, Integral Port Seal
Fits: R.V.I. Trucks; Volvo Trucks
Replaces: Volvo 20998367; Donaldson P559628; Fleetguard FS19735
Thread: 1-14
O.D.: 3 21/32 (92.9)
Length: 5 5/8 (142.9)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1383-O



Contains: Port Thread: B80 x 3.0
Fits: DAF Engines, Trucks; Doosan, Terex Equipment
Replaces: M.A.N. 51.12501.7288, 51.12503.0052; Daewoo K1006529; CLARCOR Filtration (China) WBF219
Thread: 1-14
O.D.: 4 9/32 (108.7)
Length: 9 3/32 (231.0)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1386-O



Contains: Port Thread: M80 x 2.5, Integral Port Seal
Fits: Mack, Volvo Engines, Trucks
Replaces: Mack 21017305; Volvo 20879806
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 3/16 (131.8)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1387-O




Contains: Port Thread: M80 x 2.5, Integral Port Seal
Fits: Volvo Engines, Trucks
Replaces: Volvo 20879812
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 5/16 (160.3)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1388-O



Contains: Port Thread: M95 x 2.5, Integral Port Seal
Fits: R.V.I., Volvo Trucks
Replaces: R.V.I. 7420851191; Volvo 20853583; Racor R60T-D-MAX
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 1/8 (130.2)
I. Gskt.: [1] Included
O-Ring: [2] Included

BF1389-O



Contains: Port Thread: 3 3/4-10, Integral Port Seal
Fits: Volvo Engines, Trucks
Replaces: Volvo 20381204; Racor R45T; Donaldson P550746; Fleetguard FS19734
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 3 17/32 (89.7)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1390-O



Contains: Port Thread: 3 3/4-10
Fits: Volvo Trucks
Replaces: Racor R90T; Volvo 20450423; Fleetguard FS19551
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 3/16 (157.2)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1391-O



Contains: Port Thread: M95 x 2.5
Fits: Mercedes-Benz Engines, Trucks
Replaces: Mercedes-Benz 4771302, A0004771302; Fleetguard FS19914
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 8 21/32 (219.9)
I. Gskt.: [1] Included
O-Ring: [1] Included
Related To: BF1359-SP (Sensor Port Version, without Open Port for Bowl)

BF1398-O



Notes: Inside-Out Flow Direction
Contains: Port Thread: M80 x 2.5, Integral Post Seal
Fits: Volvo Trucks with D6B Engine
Replaces: Volvo 20386080; Racor R25P; Fleetguard FS19704
Thread: 1-14
O.D.: 3 21/32 (92.9)
Length: 5 5/8 (142.9)
O-Ring: [1] Included

QUICK CROSS-REFERENCE

BALDWIN	DONALDSON	FLEETGUARD	HENGST	LUBER-FINER	MANN & HUMMEL	RACOR	BALDWIN	DONALDSON	FLEETGUARD	HENGST	LUBER-FINER	MANN & HUMMEL	RACOR
BF1222-O	P553375	FS1281	-	LFF5824B	-	R42	BF1345-O	P550729	FS19547	-	LFF3579	-	R43
BF1223-O	P550730	FS1287	-	LFF8063	-	R60T	BF1346-O	P550554	FS19593	-	LFF5850	-	S3226P
BF1287-O	-	-	-	-	-	-	BF1348-O	P550436	FS19521	-	LFF5849	-	S3225P
BF1288-O	P550937	-	-	-	-	-	BF1366-O	P559628	FS19735	H700WK	LFF3293	WK94033X	R260P
BF1290-O	-	-	-	-	-	-	BF1383-O	P550778	FS19769	H710WK	LFF9769	PL420X	-
BF1292-O	-	FS19950	H7091WK10	-	-	R90T-D-MAX	BF1386-O	P550913	FS19918	-	LFF3358	-	-
BF1294-O	-	-	-	-	-	-	BF1387-O	-	FS19920	H7091WK30 D199	-	-	-
BF1295-O	-	-	-	-	-	-	BF1388-O	-	FS19895	H7063WK30	-	WK10401X	R60T-D-MAX
BF1296-O	-	FS19907	H304WK	-	PL270X	-	BF1389-O	P550746	FS19734	-	-	WK1020X	R45T
BF1297-O	-	-	-	-	-	-	BF1390-O	P550747	-	H7090WK10	-	WK10605X	R90T
BF1299-O	-	-	-	-	-	-	BF1391-O	-	FS19914	H701WK	-	WK10807X	R160T
BF1329-O	P550747	FS19532	H7090WK30	-	WK10603X	R90P	BF1398-O	-	FS19704	H7025WK30	-	WK94032X	R25P